





**Water Absorption Dye Test:**

Over a 48 hr period we left this piece of sandstone sitting in a basin of water, with red dye added. The left hand side of the sandstone was left unsealed, and the right hand side was pre sealed on both sides with Solutions Sealers **Consolidate**, and then sealed on the top side with our commercial grade sealer **Quantum**.



As you can see above after 48hr the non sealed area has been completely stained red.



From the pictures shown above, the unsealed area has high levels of moisture. But when testing the sealed area, we discovered no moisture was apparent.